



Fig. 1



*Fig. 2*







Fig. 3

Fig. 4



A schematic diagram showing a cross-sectional view of a mechanical assembly. The assembly includes a vertical shaft 31. A horizontal member 45 is positioned above the shaft. Various components are labeled: 33a, 33b, 33c, 46, 47, 48, 49, 49a, 49b, 49c, 49d, 49e, 49f, 49g, 49h, 49i, 49j, 49k, 49l, 49m, 49n, 49o, 49p, 49q, 49r, 49s, 49t, 49u, 49v, 49w, 49x, 49y, 49z, 62, 63, and S. The diagram illustrates the internal structure and alignment of these parts.




Fig. 6




Fig. 7





Fig. 8





*Fig. 9*

